

# The Saylor House: 1975, 2019 and Today



#1. Saylor House in 1975 ten years after abandonment, original door still exists.

## Photos from 2021



#2. entering Kiwanis Park

## Photos from February 2024



#3. looking up at house from Park path



#4. House as seen from parking





#5. north gable of kitchen ell



#6. east side & chimneys, soffit, lack of gutters



#7. east side of kitchen ell with kitchen window



#8. east gable of main house



east gable with new window framing and doors



#9. south side, with new porch foundation



south side with completed porch



#10. south front with new porch wall



South front with completed porch



#11. kitchen door to breezeway, window



window covered on inside for security



#12. looking from kitchen across breezeway to back door



the replicated backdoor is leaning against the wall



#13. original brick floor



#14. Kitchen ceiling and existing roof



#15. Kitchen fireplace



original bricks used for hearth, new bricks for floor.



#16. Breezeway with door on west side



#17. breezeway, back door upper left, basement door is open.



Stairs to back door and basement; basement hatch has some original wood on right side including the pintels; strap hinges mimic shadows of hinges on original front door.



#18. backdoor, broken rafter above door



Rafter replaced, ceiling installed in breezeway



#19. breezeway roof, doorway to parking lot



Breezeway ceiling with framing repairs of doorway



#20. Soffit, fascia, molding prior to hanging gutter.

**WORKSHOPS – Instructors David Gibney and Paul Wade**



Hands on window workshop allowing participants to fix, restore and weatherize their windows



Lime plaster workshop to repair and finish the kitchen walls

